

Pictures 1 – 8 (Miscellaneous Tasks Performed Throughout the Three Bearing Changes)


Picture 1 (Bearing Check):



Picture 2 (Granite Surface):



Picture 3 (Removal of the Thrust Runner):



Picture 4 (End View of New Thrust Runner):




Picture 5 (Shaft Side of New Thrust Runner):



Picture 6 (Mushroom Check Close-up):



Picture 7 (Mushroom Check with Hydraulic Ram):



Picture 8 (Mushroom Check):

